


CORNER RECORD

Document Number APN 058-111-13

City of MILL VALLEY County of Marin California.

Brief Legal Description: LANDS OF MALLI, AS PER D. N. 12-006905



CORNER TYPE:

Government Corner Control
Meander Property
Rancho Other
Date of Survey May 14, 2012

COORDINATES [Optional]

N> _____
E> _____
Zone _____ Datum _____
Elev> _____

CORNER:----- Left as found Found & Tagged Established Reestablished Rebuilt

Identification & Type of Corner Found: Evidence used to identify or procedure used to establish or reestablish the corner:

FND. EXISTING WELL MONS. PER 11 RM 37

A description of the physical condition of the monument as found and as set or reset:

SET 5/8" REBAR & CAP, RCE# 18200 AT LOCATIONS SHOWN ON REVERSE.

SURVEYOR'S STATEMENT

The corner record was prepared by me or under my direction in conformance with the Land Surveyors' Act on MAY 14 2012

Signed: Douglas J. Matteson PLS or RCE # 18200



COUNTY SURVEYORS STATEMENT

This corner record was received: JUNE 11 2012

and examined and filed JULY 23 2012

Signed [Signature] Title: COUNTY SURVEYOR



COUNTY SURVEYOR'S COMMENT _____



SCALE: 1"=40'

LANDS OF MALLI
BEING LOT 8, 11 RM 37
223 ROUND HILL RD.
TIBURON, CA 94920
APN 058-111-13 MAY 2012

LOT 8
11 RM 37

SET NAIL & TAG RCE
18200 IN FENCE RAIL

S50° 06' 00"W
124.00'

N58° 04' 00"W
166.81'

65.15'

10.00'
P.U.E.

241.78'
104.15'
S60° 08' 00"E

N13° 36' 00"E
114.93'

10.00'
P.U.E.

ROUND HILL RD

207.74'
S13° 36' 00"W

207.74'

73.97'

25.00'
25.00'

18.83'

72.48'

25.00'
25.00'


- LEGEND
- SET REBAR AND CAP RCE 18200 U.N.O.
 - FOUND HUB & TAG, LS 6649 PER CORNER RECORD 058-111-14

SURVEY BOUNDARY

10' PUBLIC UTILITY EASEMENT
PER 11 RM 37

U.N.O. [UNLESS NOTED OTHERWISE]

- FND STD. STREET WELL MON. [BASIS OF BEARING]



D MATTESON CIVIL ENGINEER
MAY 2012 SCALE: 1"=40'