


CORNER RECORD

Document Number APN 58-121-26

City of TIBURON

County of MARIN, California

Brief Legal Description PARCEL "D" 18 PM 75



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 12/4/98

COORDINATES
(Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
RESET PROPERTY CORNER MONUMENTS ALONG N'LY AND
W'LY LINES OF PARCEL "D", 18 PM 75", PER RECORDED
BEARINGS AND DISTANCES FROM FOUND CORNER MONUMENTS
ALONG W'LY BOUNDARY OF PARCEL "A" 18 PM 75

A description of the physical condition of the monument as found and as set or reset:
SET 1/2" IRON REBAR W/PLASTIC CAP STAMPED "LS 6135" AND
SET LEAD PLUG W/BRASS TAG STAMPED "LS 6135" AS INDICATED
ON SKETCH, PAGE 2. FOUND 1" IRON PIPE W/TAG "LS 2738, 3/4" IRON
PIPE W/TAG "LS 3715, HUB TAG RE 3230, AND 2" IRON PIPE W/TAG, ILLEGIBLE
(SEE 18 PM 75, WESTERLY LINE PARCEL "A")

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyors' Act on 12/15 1998.


Signed Richard F. Aispach L.S. or R.C.E. Number 6135



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 12/21 1998 and examined
and filed 12/24 1998.

Signed John M. Wooley Title Deputy



County Surveyor's Comment _____