


CORNER RECORD

Document Number 3570-OR-113

City of Tiburon

County of MARIN, California

Brief Legal Description Lot 22, "Map of El Marinero", 14-MAPS-25



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 29 October 1999

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found standard street monuments with nail & tag "RCE 12510" per 14-MAPS-25

(A) Found lead plug with tag "LS 3887"

(B) Found 1" plastic pipe with plastic cap "LS 3887"


A description of the physical condition of the monument as found and as set or reset: _____

(B) Set lead plug with bronze nail & tag "LS 4794"; (C) Set 1 1/2" x 1 1/2" redwood hub with bronze nail & tag "LS 4797"; (D) Set 3/4" I.D. galvanized iron pipe with plastic plug "PLS 4794 DANSKIN"; (E) Set concrete nail & tag "LS 4794"

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 1 November 1999.

Signed [Signature] L.S. or R.C.E. Number LS 4794



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received November 3 1999 and examined and filed November 5 1999.

Signed [Signature] Title Deputy



County Surveyor's Comment _____