


CORNER RECORD

Document Number APN 59-032-26

City of Tiburon County of Marin, California

Brief Legal Description Lot 4, Map of Moitoza Subdivision, 19 RM 53, M.C.R.



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 11/4/1999

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Reestablish the lot corners (excepting the most Northeasterly and most
Northwesterly corner) of Lot 4 of the Map of Moitoza Subdivision
19 RM 53, Marin County Record; reestablished from existing found points
of the exterior of said lot 4 and as shown in further detail in the
sketch on the reverse side of this page.

A description of the physical condition of the monument as found and as set or reset: Set one half inch
rebar with yellow plastic cap affixed to top and embossed with PLS 5379
Scranton, (unless as noted otherwise on the sketch on the reverse side
of this sheet..

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyors' Act on November 5th 19 99.

Signed *Douglas J. Scranton* L.S. or R.C.E. Number PLS 5379
 renewal 6/30/00



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received NOVEMBER 9 1999 and examined
 and filed NOVEMBER 10 1999.

Signed *John M. Woolley* Title DEPUTY



County Surveyor's Comment _____

PREPARED BY DJ SCRANTON SURVEYING 845 OLIVE AVE. SUITE 208 NOVATO, CA 94945 897-2663

