


CORNER RECORD

Document Number APN 59-201-42

City of TIBURON County of MARIN, California

Brief Legal Description DN 93-072390 AS SURVEYED PER 32 OS 92



CORNER TYPE

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey May 25, 1999

COORDINATES  
(Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ Datum \_\_\_\_\_  
Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:


THE PURPOSE OF THIS CORNER RECORD IS SHOW REESTABLISHED EASTERLY LOT OF THE LAND OF GEHRMANN AS PREVIOUSLY SURVEYED BY THIS OFFICE IN JULY OF 1994 AND RECORDED PER 32 OS 92, MARIN COUNTY RECORDS. THIS CORNER RECORD SHOWS LOT LINE POINTS SET ALONG THE EASTERLY LOT LINE (REFER TO DETAIL ON REVERSE SIDE). THE EXISTING END POINTS OF 32 OS 92 WERE FOUND AND UTILIZED TO RECREATE THE LINE AS PREVIOUSLY SURVEYED BY THIS OFFICE.

A description of the physical condition of the monument as found and as set or reset: AT NORTHERLY TERMINUS OF LINE SET BRASS TAG LS 5379 IN CONCRETE CYCLINDER MONUMENT; ALONG LOT LINE SET ONE HALF INCH REBAR WITH PLS CAP 5379 AND DRIVEN FLUSH WITH EXISTING GRADE. AT CYPRESS TREE NEAR SOUTHERLY LOT CORNER SET PK NAIL IN NORTHERLY FACE OF TREE ABOUT 3 FEET ABOVE GROUND.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on June 7th 19 99.

Signed Douglas J. Scranton L.S. or R.C.E. Number 5379  
Douglas J. Scranton renewal date 6/30/00



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUGUST 2 19 99 and examined and filed AUGUST 10 19 99.

Signed [Signature] Title DEPUTY



County Surveyor's Comment \_\_\_\_\_

PREPARED BY: DJ SCRANTON SURVEYING 845 OLIVE AVE. NO. 208 NOVATO, CA 94945 (415) 897-2663