


**Lands of Shone**  
**Job #: 02-661**

**CORNER RECORD**

Document Number 060-011-19

City of Belvedere , County of Marin , California

Brief Legal Description: Lot 19, "Map of Hilarita Lagoon Sites" 5 RM 89



**CORNER TYPE**

**COORDINATES (Optional)**

Government Corner  Control

Meander  Property

Rancho  Other

Date of Survey November 20, 2002

N \_\_\_\_\_

E \_\_\_\_\_

Zone \_\_\_\_\_ NAD27  NAD83

NAD 83 Epoch

Elev. \_\_\_\_\_

Vert. Datum: NGVD29  NAVD88

Meas. Units: Metric  Imperial

**Corner -** Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
See Page 2 of 2 "Plat of Survey"

A description of the physical condition of the monument as found and as set or reset:  
See Page 2 of 2 "Plat of Survey"

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with

The Land Surveyor's Act on November 21, 2002.

Signed [Signature] P.L.S. 6649



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received DECEMBER 2, 2002

and examined and filed DECEMBER 10, 2002

Signed [Signature] P.L.S. or R.C.E. No. 7128

Title DEPUTY

County Surveyors' Comment \_\_\_\_\_

