


CORNER RECORD

Document Number 060-011-21

City of Belvedere County of Marin, California

Brief Legal Description Lot 21, Map of "Hilarita Lagoon Sites" 5 RM 89



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 12-21-2000

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

See "Plat of Survey" Page 2 of 2.


A description of the physical condition of the monument as found and as set or reset:

See "Plat of Survey" Page 2 of 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on January 2, 2001

Signed [Signature] P.L.S. or R.C.E. No. 6649



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JANUARY 4, 2001

and examined and filed JANUARY 8, 2001

Signed [Signature] P.L.S. or R.C.E. No. 7128

Title DEPUTY

County Surveyor's Comment _____

