


CORNER RECORD

Document Number APN 060-031-32

City of BELVEDERE

County of Marin California

Brief Legal Description: LOT 8 LAGOON SUB. # 4: BK 7 R.M. P 1



CORNER TYPE:

Government Corner Control
 Meander Property X
 Rancho Other
 Date of Survey _____

COORDINATES

[Optional]

N> _____
 E> _____
 Zone _____ Datum _____
 Elev> _____

CORNER --LEFT AS FOUND FOUND & TAGGED ESTABLISHED REESTABLISHED REBUILT

Identification & Type of Corner Found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND EXISTING MONUMENTS AS SHOWN ON REVERSE MAP

A description of the physical condition of the monument as found and as set or reset: SET REBAR & CAP,

RCE# 18200, AT LOCATIONS SHOWN ON REVERSE.

SURVEYOR'S STATEMENT

The corner record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on MAY 1 1998

Signed: Douglas J. Matteson LS or RCE # 18200



COUNTY SURVEYORS STATEMENT

This corner record was received: JUNE 5 1998

and filed JUNE 5 1998

Signed: John M. Woolley Title: DEPUTY



COUNTY SURVEYOR'S COMMENT _____