

**CORNER RECORD**


Document Number 90-39077

City of BELVEDERE

County of MARIN, California

Brief Legal Description LOT 12 6-RM-77

AP # 060-111-03



**CORNER TYPE**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 3/15/2001

**COORDINATES (Optional)**

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

RAILROAD SPIKE CENTERLINE MONUMENTS  
AS SHOWN ON REVERSE.

A description of the physical condition of the monument as found and as set or reset:


SET PROPERTY CORNERS AS SHOWN ON  
REVERSE.

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on May 31 2001

Signed William Schroeder P.L.S. or R.C.E. No. PS 5814



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received JULY 2, 2001

and examined and filed JULY 3, 2001

Signed [Signature] P.L.S. or R.C.E. No. 7128

Title DEPUTY



County Surveyor's Comment \_\_\_\_\_