


CORNER RECORD

Document Number A.P. 060-142-06, 060-162-14

City of BELVEDERE

County of MARIN, California

Brief Legal Description LOTS 6 & 7 PER 5 R.M. 68



CORNER TYPE

COORDINATES (Optional)

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 07/02/08

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
REESTABLISHED NORTHERLY AND EASTERLY CORNERS OF LOT 6, THE NORTHEASTERLY LINE OF LOT 7,
AND THE SOUTHEASTERLY AND NORTHWESTERLY LINES OF LOT 6, AS SHOWN ON SHEET 2.

A description of the physical condition of the monument as found and as set or reset: SEE SHEET 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on JULY 2 2008

Signed Lawrence P Doyle P.L.S. or R.C.E. No. P.L.S. 4694



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received SEPTEMBER 17, 2008

and examined and filed OCTOBER 14, 2008

Signed [Signature] P.L.S. or R.C.E. No. 7128

Title COUNTY SURVEYOR

County Surveyor's Comment _____

