


CORNER RECORD



JERRICO ASSOCIATES
SUITE 27
77 MARK DRIVE
SAN RAFAEL, CA 94903

7111

City of Belvedere Document Number 60-155-03
County of Marin, California
Brief Legal Description Lot 8, Block 8, Map No. 4 Belvedere Peninsula
Rack 1 Pull 11



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey Dec. 29, 1994

COORDINATES
(Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Retracement of survey points shown in 19 OS 100

- (B) Found RR spike
- (C) Found nail & tag (illegible) in asphalt walk.
- (E) Found 3/4" IP RCE 11181
- (F) Fence corner per 19 OS 100
- (D) Found 3/4" IP LS 3971

A description of the physical condition of the monument as found and as set or reset:

- (G) Set #5 Rebar and cap LS 3887
- (H) " " " " " "
- (J) Set brass tag stamped "L.S.3887" in top fence runner

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on December 29 19 94.

Signed [Signature] L.S. or R.C.E. Number LS 3887

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 1-27 19 95 and examined and filed 1-27 19 95.

Signed [Signature] Title DES

County Surveyor's Comment _____

