


# CORNER RECORD

Document Number A.P.N. 060-161-01

City of Belvedere

County of Marin, California

Brief Legal Description Lands of Belvedere, LLC, 39 Belvedere Avenue, 2007 OS 114.



## CORNER TYPE

Government Corner ☐ Control ☐  
Meander ☐ Property ☒  
Rancho ☐ Other ☐

Date of Survey 9 September 2011

## COORDINATES(Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27 ☐ AD83 ☐  
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29 ☐ NADV88 ☐  
Meas. Units: Metric ☐ Imperial ☐

Corner - Left as found ☐ Found and tagged ☐ Established ☒ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
Found Standard Street Monuments (2), on Belvedere Avenue in Belvedere per 2007 OS 114.


A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_

Set 3/4" Iron Pipe on most southerly corner, 1/2" Rebar on most northerly corner, a concrete nail in edge of pavement on the northwesterly line, a painted X on 8" sanitary sewer pipe on the northwesterly line and a painted X on concrete on the northwesterly line, See Exhibit "A".

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with  
the Land Surveyor's Act on OCTOBER 19, 2011.

Signed [Signature] P.L.S. or R.C.E. No.: 18221



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received SEPTEMBER 16, 2011 and examined  
and filed OCTOBER 25, 2011.

Signed [Signature] P.L.S. or R.C.E. No.: 7128

Title COUNTY SURVEYOR

County Surveyor's Comment \_\_\_\_\_



