CORNER RECC			CORD	Agency Index	CR24-031	
				Document Number	060-182-27	
City of	BEL	VEDERE	County of	MARIN	, California	
Brief L	egal Descriptio		THAT RECORD OF S	URVEY RECORDED IN B		
CORNER TYPE				COORDINATES (Optional)		
<u> </u>				N	E/	
	Government Corner Control			Elevation		
		Meander	X Property	Units 🗌 Metric	U.S. Survey Foot	
		Rancho	C Other	Horizontal Datum		
				ZoneE	och Date	
		Date of Survey	11/13/2023	Vertical Datum		
		_		Complies with Public	Resources Code §§8801-8819	
				Complies with Public	Resources Code §§8890-8902	
PLS Act	Ref.:	8765(d)	8771	8773	Other:	
Corner/	X	Left as found	Established	Rebuilt	Pre-Construction	
Monume	ent:	Found and tagged	X Reestablished	Referenced	Post-Construction	
Narrative	e of corner identifi	ed and monument as fou	nd, set, reset, replaced,	or removed:		

X See sheet #2 for description(s):

FOUND 1/2" REBARS AND A 2" BRASS DISK IN A MONUMENT WELL, AS SHOWN ON THAT RECORD OF SURVEY RECORDED IN BOOK 2007 OF MAPS, AT PAGE 215, MARIN COUNTY RECORDS. RAILROAD SPIKE AT NORTHEAST CORNER OF SUBJECT PARCEL WAS SEARCHED FOR, BUT NOT FOUND. SET A NAIL AND 1.5" BRASS DISK, STAMPED PLS 8155 AT THE NORTHEAST CORNER OF THE SUBJECT PARCEL. SEE SHEET 2 FOR MORE DETAILS.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on	3/28/2024		
Signed Stertler	P.L.S. or <b>B.C.E</b> . No.	8155	



COUNTY SURVEYOR'S STATEMENT

This Corr	her Record was rece	Iviarch	28, 2024		
and exan	nined and filed	March 29, 2024	1		
Signed	T.L.F		P.L.S.	No. <u>8176</u>	
Title	County Survey	or			



**County Surveyor's Comment** 

