


CORNER RECORD

Document Number A.P.N. 60-232-03

City of Belvedere

County of Marin, California

Brief Legal Description Record of Survey 9 OS 90



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey _____

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found monument at the most Southerly corner and at Southwesterly terminus of Northwesterly Boundary Line.

A description of the physical condition of the monument as found and as set or reset:

Set 3/4" iron pipe and plug "RCE 18221" at Northwesterly terminus of Southwesterly line.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on JUNE 1, 2001

Signed [Signature] P.L.S. or R.C.E. No. 18221

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUNE 4, 2001

and examined and filed JUNE 5, 2001

Signed [Signature] P.L.S. or R.C.E. No. 26450

Title DEPUTY

County Surveyor's Comment _____

