


CORNER RECORD

Document Number A.P. 60-281-11

City of BELVEDERE

County of MARIN, California

Brief Legal Description LOT 21 PER 11 R.M. 50



CORNER TYPE

Government Corner Control

Meander Property

Rancho Other

Date of Survey 3/6/08

COORDINATES (Optional)

N. _____
E. _____

Zone _____ NAD27 NAD83
NAD83 Epoch _____

Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
ESTABLISHED LOT 21 USING FOUND STREET MONUMENTS ON WEST SHORE ROAD PER 11 R.M. 50 AND
AS SHOWN ON SHEET 2.


A description of the physical condition of the monument as found and as set or reset: SEE SHEET 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on MARCH 7 2008

Signed Lawrence P. Doyle P.L.S. or R.C.E. No. P.L.S. 4694



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MARCH 24, 2008

and examined and filed APRIL 30, 2008

Signed [Signature] P.L.S. or R.C.E. No. 7128

Title COUNTY SURVEYOR



County Surveyor's Comment _____

