


CORNER RECORD

Document Number 060-281-11

City of Belvedere

County of Marin, California

Brief Legal Description Lot 21, West Shore Subd. No.2, 11 RM 50.



CORNER TYPE

Government Corner Control
Meaneder Property
Rancho Other
Date of Survey 12/28/2015

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found centerline monuments per West Shore Sub'd. No. 2, 11 RM 50, M.C.R., to be in record position and used to set monuments (see attached Sheet 2).

A description of the physical condition of the monument as found and as set or reset:

Set (1)nail and (1)5/8"rebar as points on line (see attached Sheet 2).

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on 06/09/16

Signed Michael E. Ford P.L.S. or R.C.E. No. 7237



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUNE 15, 2016


and examined and filed SEPTEMBER 23, 2016

Signed Richard G. Simonitch P.L.S. or R.C.E. No. 7821

Title County Surveyor



County Surveyor's Comment



(IN FEET)
1 inch = 40 ft.

LEGEND

- FOUND STREET MONUMENTS
- ⊗ FOUND BRASS TAG IN CONC., LS4694, PER CORNER RECORD FILED ON 12/31/08
- ⊙ SET POINT ON LINE, AS NOTED
- (RAD) RADIAL

BASIS OF BEARINGS

S07°22'12"E BETWEEN FOUND CENTERLINE MONUMENTS SHOWN ON 11 RM 50, M.C.R.

BASIS OF BEARINGS

ALL BEARINGS AND DISTANCES ARE RECORD AND MEASURED PER WEST SHORE SUBD. NO. 2, 11 RM 50, M.C.R.



2300 bethards drive, suite J
santa rosa, california 95405
p 707.542.8513 - f 707.542.1825
www.michaelfordinc.com

