


CORNER RECORD

Document Number A.P.N. 063-010-02

City of SAUSA LITO

County of MARIN, California

Brief Legal Description PORTION OF LOT 8 PER 2 O.S. 127; ALSO THE SUBJECT PARCEL OF 7 O.S. 20



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 12-17-99

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

= SEE OVER =

A description of the physical condition of the monument as found and as set or reset:

= SEE OVER =

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 12-30 1999.


Signed David Contreras L.S. or R.C.E. Number 5065



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received January 4 ²⁰⁰⁰/₁₉ and examined and filed January 6 ²⁰⁰⁰/₁₉

Signed John M. Wooley Title Deputy



County Surveyor's Comment _____