


**CORNER RECORD**

Document Number 064-141-20

City of SAUSALITO

County of MARIN, California

Brief Legal Description LOT 1, 36 ROS 77



**CORNER TYPE**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey JUNE 6, 2000

**COORDINATES (Optional)**

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SEE "CORNER RECORD PLAT", PAGE 2 OF 2.

A description of the physical condition of the monument as found and as set or reset:

SEE "CORNER RECORD PLAT" PAGE 2 OF 2.

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on JUNE 23 2000.

Signed [Signature] P.L.S. [REDACTED] No. 6649



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received JUNE 29, 2000

and examined and filed JULY 6, 2000

Signed [Signature] P.L.S. or R.C.E. No. 26450

Title DEPUTY



County Surveyor's Comment \_\_\_\_\_