


CORNER RECORD

Document Number \_\_\_\_\_

City of SAUSALITO County of MARIN, California

Brief Legal Description 20 R.M. 73 ; PCL. 3 14 P.M. 3



CORNER TYPE

- Government Corner
- Meander
- Rancho
- Date of Survey \_\_\_\_\_
- Control
- Property
- Other

COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND WELL MONS SHOWN ON MAP

A description of the physical condition of the monument as found and as set or reset: Set 5/8 Rebar & PLASTIC CAP RCE #18200

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 4-1 1997.


Signed Douglas J. Matteson L.S. or R.C.E. Number 18 200



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received APRIL 22 1997 and examined and filed APRIL 28 1997.

Signed John M. Wooley Title Deputy



County Surveyor's Comment \_\_\_\_\_