


# CORNER RECORD

Document Number APN 064-211-32  
County of Marin, California

City of Sausalito

Brief Legal Description Easterly corner of Lot 9 per 17 Maps 82



### CORNER TYPE

Government Corner  Control   
Meander  Property   
Rancho  Other

Date of Survey January 12, 2017

### COORDINATES (Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

In compliance with Section 8771 of the Professional Land Surveyors' Act, this corner record is being filed to ESTABLISH the position of an existing monument PRIOR to construction.

A description of the physical condition of the monument as found and as set or reset:

See sketch on back.

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyor's Act on February 7, 2017


Signed Robert S. Sullivan P.L.S. or R.C.E. No. LS 8558



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received April 5, 2017  
and examined and filed MAY 17, 2017

Signed [Signature] P.L.S. or R.C.E. No. 9292  
Title DEPUTY C.S.



County Surveyor's Comment: \_\_\_\_\_

