


CORNER RECORD

Document Number APN 64-221-14

City of SAUSALITO

County of MARIN, California

Brief Legal Description LOT 6-A, 205.173 APN. 64-221-14



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey _____

**COORDINATES
(Optional)**

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
FOUND 3/4" I.P. "LS. 5296" UNDISTURBED AS NOTED ON SKETCH.
FOUND STD. STREET MONUMENTS AS SHOWN ON 205.173 AND
MEASURED PER RECORD. USED FOR RECORD LOCATION OF SET
CORNERS AS INDICATED.

A description of the physical condition of the monument as found and as set or reset:
MONUMENT IN GOOD CONDITION. SET 1/2" IRON PIN WITH CAP "PL56234" AS
INDICATED. SET CROSS CUTS IN CONCRETE ALONG TOYON LANE
FRONTAGE. SET NAIL & TAG "LS6234" IN TOP 2" IRON PIPE FENCE
CORNER CAP.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyors' Act on JUNE 30 19 98.

Signed [Signature] L.S. or R.C.E. Number PL56234



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JULY 2 19 98 and examined
and filed JULY 2 19 98.

Signed [Signature] Title DEPUTY

County Surveyor's Comment _____

