


CORNER RECORD

Document Number 64-221-41

City of SAUSALITO County of MARIN, California

Brief Legal Description A PORTION OF LOTS 2 & 3, BLOCK 35, RACK 1 PULL 9



CORNER TYPE

**COORDINATES
(Optional)**

Government Corner Control
Meander Property
Rancho Other
Date of Survey 6-13-94

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
FOUND STANDARD STREET MONUMENTS AS SHOWN ON 19 PM 75
AND 30 OS 93. RESET SOUTHEASTERLY LINE OF PARCEL 'A', 19 PM
75 AT RECORD POSITIONS.

A.P. No 64-221-41

A description of the physical condition of the monument as found and as set or reset: SET 3/4" IRON
PIPE TAGGED P.L.S. 5296

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JUNE 14, 1994.

Signed Steven H. Jacobs L.S. or R.C.E. Number P.L.S. 5296



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 6-17 1994 and examined and filed 6-20 1994.

Signed R. D. Beech Title DES



County Surveyor's Comment _____