


**CORNER RECORD**

Document Number AP 064-231-24

City of SAUSALITO

County of MARIN, California

Brief Legal Description PARCEL 1, 11 P.M. 17



**CORNER TYPE**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey MAY 29, 1999

**COORDINATES (Optional)**

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2 OF 2.

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2 OF 2.

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on JUNE 7, 1999

Signed [Signature] P.L.S. or [Redacted] No. 6649



6-8-99


**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received JUNE 14, 1999

and examined and filed JUNE 18, 1999

Signed [Signature] P.L.S. or R.C.E. No. 26450

Title DEPUTY



County Surveyor's Comment \_\_\_\_\_