


CORNER RECORD

City of Sausalito Document Number 064-241-01
 County of Marin, California
 Brief Legal Description Lot 41 of SRM 71



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 12/21/07

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found monuments shown on 2004 Maps (RS) 189, Marin County Records.

A description of the physical condition of the monument as found and as set or reset:
Found 5/8" rebars & caps LS 5290, and set 1/2" rebars & caps LS 5290 (see sketch map-over)


SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 12/21/07
 Signed David Harp L.S. or R.C.E. Number 5290



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 1-2-2008 and examined
 and filed 1-30-2008
 Signed [Signature] Title COUNTY SURVEYOR



County Surveyor's Comment: _____

