


CORNER RECORD

Document Number A.P.N. 64-301-10
County of MARIN, California

City of SAUSALITO

Brief Legal Description LOT 44 10 R.M. 65 A.P. 64-301-10



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey _____

**COORDINATES
(Optional)**

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

REESTABLISHED THE LOT CORNERS FROM THE
STREET MONUMENTS SHOWN 10 R.M. 65

A description of the physical condition of the monument as found and as set or reset: _____

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on SEPTEMBER 1999.


Signed Lawrence P. Doyle L.S. or R.C.E. Number P.L.S. 4694



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received SEPTEMBER 20, 1999 and examined and filed SEPTEMBER 22, 1999.

Signed John M. Wooley Title DEPUTY



County Surveyor's Comment _____