APH 065-164-11

CORNER RECORD	Document Number	20 PM	78
City of SAUSALITO	County of	MARIN	, California
Brief Legal Description PARCEL Z, 20 P.	MAR, BT.M.	IN COUNTY	RECORDS
CORNER TYPE	: Control □	(Opt	DINATES ional)
Meander	Property 🔀 Other 🔲	E Da	atum
Corner — Left as found Found and tagged	Established 🔀 🛚 F	Reestablished [Rebuilt []
Identification and type of corner found: Evidence used to ide	ntify or procedure used t	o establish or reestab	lish the comer:
CORNER IDENTIFIED AS "A			
THIS SHEET SET PER MC			
UPON "PARCEL MAP LANDS O	OF LAPIN BEI	ING A POR	27101
OF BLOCK 4 SAUSALITO LAND A	1NO FERRY	6,5AUS	ALITO"
TLED IN BOOK 20 OF PARCELL			
A description of the physical condition of the monument as		•	
AT CORNER "A" SET A CON			
"LS 4788" IN A FLACST		- WONE	100
LOTICO N ATLACS	ONE TENT	0,	
		 	
SURVEYOR'S STATEMENT		THE THE PARTY OF T	AND SUAL
This Corner Record was prepared by me or under my dire		I hour	BHEYFOGLE
the Land Surveyors Act on APRIL 15		* N	0.4788 x
Signed L.S. or R.C.E. Nu	ımber <u>LS 4788</u>	- Ville	CALIFORNIE
COUNTY SURVEYOR'S STATEMEN	NT		TANDS
This Corner Record was received APRIL 18, 200	L_{-} 49 $-$ and examin	ned 📆	TACATE PA
and filed A PRIL 19, 2001 19			SEAL Y
Signed Titl	e DEPUTY		No. 7128
County Surveyor's Comment			GE CALIFO
			· · · · · ·

