CORNER RECORD	APNº 65-231-24
O_{h} as	Document Number 60T 96 3 Rm 86
City of SAUSACITO County of MARIN , California Legal Description LOT 46 3 Rm 86	
Meander 🔲	COORDINATES (Optional) Control
Corner — Left as found [] Found and tagged []	Established Reestablished Rebuilt
A description of the physical condition of the monument as fo	of CUT 46 3 Rm 86 per 19 Rm 83 ound and as set or reset:
SURVEYOR'S STATEMENT	
This Corner Record was prepared by me or under my direct the Land Surveyors' Act on	ber <u>LS 6344</u> 3 3 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7
This Corner Record was received <u>SEPT. 30 2.002</u>	19 and examined
and filed <u>OCTOBER 4, 2002</u> 19	
SignedTitle	DEPUTY SED LAND SUPERIOR TACKYEE
County Surveyor's Comment	No. 7128 ST
er transport	

