


**CORNER RECORD**

Document Number A.P.# 65-242-02  
County of MARIN, California

City of SAUSALITO

Brief Legal Description LOTS Nos 7 & 8 3 R.M. 86 Block No. 3



**CORNER TYPE**

- Government Corner
- Meander
- Rancho
- Date of Survey \_\_\_\_\_
- Control
- Property
- Other

**COORDINATES (Optional)**

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ Datum \_\_\_\_\_  
Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
ESTABLISHED corners of LOTS 7 & 8, Block 3, 3 R.M. 86  
using 19 O.S. 58 and the found points thereof  
as shown

A description of the physical condition of the monument as found and as set or reset:  
See drawing. Corners falling in beach area  
were offset along property lines


**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on Sept 20 1995.  
Signed Michael A. Brogan L.S. or R.C.E. Number LS 5767



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received Sept. 22 1995 and examined and filed 9-25 1995.  
Signed [Signature] Title DCS



County Surveyor's Comment \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

● = Found Nail & Tag - LS 2897 as per 19 D.S. 58  
 ○ = set 1/2" rebar with plug : LS 5767  
 unless otherwise noted

