


**CORNER RECORD**

Document Number 065-252-30  
County of MARIN, California

City of SAUSALITO  
Brief Legal Description LOT 157 3 RM 86



**CORNER TYPE**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey \_\_\_\_\_

**COORDINATES (Optional)**

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
RETRACEMENT OF 3 RM 86

A description of the physical condition of the monument as found and as set or reset:  
FOUND STD STREET MONUMENTS  
SET: 1/2" REBAR & CAP LS 6344

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with  
the Land Surveyor's Act on JULY 2004  
Signed [Signature] P.L.S or R.C.E. No. PLS 6344

**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received JULY 18, 2007  
and examined and filed JULY 23, 2007  
Signed [Signature] P.L.S or R.C.E. No. 7128  
Title COUNTY SURVEYOR

County Surveyor's Comment \_\_\_\_\_

