


CORNER RECORD

Document Number 065-252-49752

City of SAUSALITO

County of MARIN, California

Brief Legal Description PARCEL 113 9 05 32



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey _____

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner -- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

RETRACEMENT OF 9 05 32

A description of the physical condition of the monument as found and as set or reset:

FOUND STD STREET MONUMENTS
SET 1/2" REBAR & CAP LS 6344

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on JULY 2004

Signed [Signature] P.L.S or R.C.E. No. PLS 6344

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JULY 18, 2007

and examined and filed JULY 23, 2007

Signed [Signature] P.L.S or R.C.E. No. 7128

Title COUNTY SURVEYOR

County Surveyor's Comment _____

