

CORNER RECORD


A.P. N. 70-011-08

Document Number 93-095623

City of San Rafael

County of _____, California

Brief Legal Description LOT 527 7 RM 92



CORNER TYPE

Government Corner [] Control []
Meander [] Property [X]
Rancho [] Other []
Date of Survey 2-96

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found [] Found and tagged [] Established [] Reestablished [X] Rebuilt []

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

See Sheet 2


A description of the physical condition of the monument as found and as set or reset:

See Sheet 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 4-23 1996.

Signed Linda A. Carruthers or R.C.E. Number 7053



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 4-29 1996 and examined and filed S-1 1996.

Signed [Signature] Title DCJ



County Surveyor's Comment

