


A. B. # 70-012-02

CORNER RECORD

COUNTY OF Marin T. _____ R. _____ MERIDIAN _____ CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND, EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Set 3/4" I.D. iron pipe with plastic plug "LS 3775"; at northeasterly corner of Lot 537; "Map of Greenbrae Sub No. Six"; recorded in Book 7 of Maps, at Page 92; Marin County Records.

AP No. 70-012-02 Survey No. 1674

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED



AS SHOWN

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD

STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



SURVEYOR'S CERTIFICATE

CORNER RECORD WAS PREPARED BY ME OR UNDER MY SUPERVISION IN CONFORMANCE WITH THE LAND SURVEYORS ACT

February 22 19 88

SIGNED: _____

L.S. or R.C.E. No.: LS 3775; exp 12/31/91

COUNTY SURVEYOR'S CERTIFICATE


THE CORNER RECORD WAS RECEIVED BY ME AND EXAMINED AND FILED

BY: R.P.P. 19 88

TITLE: Depository

DOCUMENT No. EX. 3-31-88

STATEMENT ON BACK OF SHEET




CORNER RECORD

COUNTY OF Marin T. _____ R. _____ MERIDIAN _____ CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND, EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Set 3/4" I.D. iron pipe with plastic plug "LS 3775"; at northwesterly corner of Lot 537; "Map of Greenbrae Sun No. Six"; recorded in Book 7 of Maps, at Page 92; Marin County Records.

AP No. 70-012-02 Survey No. 1674

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED



AS SHOWN

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD

STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT

February 23 19 88

SIGNED: _____

L.S. or R.C.E. No.: LS 3775; exp 12/31/91

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED AND EXAMINED AND FILED _____ 19 88

BY: RDP

TITLE: DEPT. CLERK

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET



CORNER RECORD

COUNTY OF Marin T. _____ R. _____ MERIDIAN _____ CALIFORNIA _____
 CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Set 3/4" I.D. iron pipe with plastic plug "LS 3775"; at southwesterly corner of Lot 537; "Map of Greenbrae Sub No. Six"; recorded in Book 7 of Maps, at Page 92; Marin County Records.



Ap No. 70-012-02 Survey No. 1674

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

AS SHOWN

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____


SKETCH: (Include reference tie or witness points, remarks and topo of area)



SURVEYOR'S CERTIFICATE
 THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT
 February 23, 1988

SIGNED: _____
 L.S. or R.C.E. No.: LS 3775; exp. 12/31/91.

COUNTY SURVEYOR'S CERTIFICATE
 THE CORNER RECORD WAS RECEIVED AND EXAMINED AND FILED _____ 19____
 BY: Debra C.30212
 TITLE: Deputy
 DOCUMENT No. EX-3-218
 STATEMENT ON BACK OF SHEET




CORNER RECORD

COUNTY OF Marin T. _____ R. _____ MERIDIAN _____ CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER RESULT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found 2 x 2 Hub with nail at southeasterly corner of Lot 537; "Map of Greenbrae Sub. No. Six"; recorded in Book 7 of Maps, at Page 92; Marin County Records.

AP No. 70-012-02

Survey No. 1674

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED



AS SHOWN

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD

STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT OF February 23 _____ 19__88

SIGNED: _____

C.S. or R.C.E. No.: LS 3775; exp. 12-31-91

COUNTY SURVEYOR'S PROFESSIONAL SEAL

THE CORNER RECORD WAS RECEIVED AND EXAMINED AND FILED BY: _____

TITLE: Depository

DOCUMENT No. _____

STATE OF CALIFORNIA

EX-2-3188

STATE OF CALIFORNIA