


CORNER RECORD

Document Number _____

City of Greenbrae

County of MARIN, California

Brief Legal Description LOT 233 OF G-RM-44 ; AP# 70-151-39



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 9-16-93

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

1. FOUND 2 (Two) STANDARD COUNTY MONUMENTS
PER G-RM-44

A description of the physical condition of the monument as found and as set or reset:

1. SET NAIL & TAG L.S. 5290

2. SET NAIL & TAG L.S. 5290
ON TOP OF FENCE

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on Sept 30th 1993.


Signed David Hays L.S. or R.C.E. Number LS 5290



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 10-4 1993 and examined and filed 10-4 1993

Signed [Signature] Title De



County Surveyor's Comment _____

