


**CORNER RECORD**

Document Number 70-182-13

City of Greenbrae

County of Marin, California

Brief Legal Description Portion of Lots 144, 145 Greenbrae Sub. No 1 & Maps 7



**CORNER TYPE**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey \_\_\_\_\_

**COORDINATES (Optional)**

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found centerline monuments as shown on Record of Survey filed in Book 2 of Official Surveys, Page 115 Marin County Records. Set property corners at record bearings and distances as shown on said map. (20S 115)

A description of the physical condition of the monument as found and as set or reset: Get 1/2" iron pipes

tagged LS 7251 at front lot corners. Set tag stamped PLS 7251 on top of fence at rear lot corners

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on July 7 2005

Signed Darrin E. Jackson P.L.S or R.C.E. No. LS 7251



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received JULY 11, 2005

and examined and filed AUGUST 12, 2005

Signed [Signature] P.L.S or R.C.E. No. 7128

Title COUNTY SURVEYOR



County Surveyor's Comment \_\_\_\_\_

