


CORNER RECORD

Document Number A.P.N. 70-313-08

City of Larkspur County of Marin, California

Brief Legal Description Lot 1546 Map of Greenbrae Sub #14 Bk. 10 O.R. P 1
Filed July 25, 1958



CORNER TYPE

- Government Corner
- Meander
- Rancho
- Date of Survey _____
- Control
- Property
- Other

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____


Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
End. Existing Mons. Set 5/8" Rebar and Plastic Cap RCE #18200. on p/1
70" from NE cor. (see map on reverse)

A description of the physical condition of the monument as found and as set or reset: _____

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on July 30 1996
 Signed D. J. Matteson L.S. or R.C.E. Number 18200



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 8-21 1996 and examined and filed 8-22 1996.
 Signed [Signature] Title DCS



County Surveyor's Comment _____

DOUGLAS J. MATTESON
 CIVIL ENGINEER & LAND
 SURVEYOR
 200 GATE 5 RD. #208
 SAUSALITO CA. 94965
 332 7614

LANDS OF PARRISH
 OF
 CORNER RECORD MAP

LOT 1546 OF MAPS
 O.R. BK 10 PAGE 1

JULY 25, 1958
 APM 70-313-08

