


CORNER RECORD

Document Number A.P.# 071-042-06

City of KENTFIELD

County of MARIN, California

Brief Legal Description PARCEL B, 22 P.M. 94



CORNER TYPE

COORDINATES (Optional)

Government Corner Control

Meander Property

Rancho Other

Date of Survey 03/12/13

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

REESTABLISHED THE SOUTHEASTERLY LINE OF PARCEL B, AS SHOWN ON 22 P.M. 94,

BASED UPON FOUND PIPES PER 22 P.M. 94, AS SHOWN ON SHEET 2

A description of the physical condition of the monument as found and as set or reset: SEE SHEET 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on MARCH 13 2013

Signed Lawrence P. Doyle P.L.S. or R.C.E. No. P.L.S. 4694



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MAY 7, 2013

and examined and filed JUNE 14th 2013

Signed Richard G. Simonitch P.L.S. or R.C.E. No. 7821

Title DEPUTY CO. SURVEYOR



County Surveyor's Comment _____

PARCEL A

10.00'

N75°13'53"W
419.29'

PARCEL B
22 P.M. 94

N35°17'10"E 196.63'
120.92'
206.63'

BASIS OF BEARING

BASIS OF BEARING


THE BASIS OF BEARING FOR THIS SURVEY IS BETWEEN FOUND PIPES PER 22 P.M. 94

N26°13'00"W
95.68'

75.71'

LEGEND

- FOUND PIPE
- FOUND PIPE & TAG, RCE 15945
- FOUND ASPHALT NAIL, PER CORNER RCD. #71-042-27
- SET 3/4" PIPE & PLUG, L.S. 4694



CORNER RECORD PARCEL B, 22 P.M. 94 KENTFIELD MARIN COUNTY CALIFORNIA		
SCALE: 1" = 30'	LAWRENCE P. DOYLE LAND SURVEYOR/CIVIL ENGINEER 100 HELENS LANE MILL VALLEY CA 94941 (415-388-9585)	DRAWN BY:
DATE: 03/12/13		SHEET 1 OF 1
		DRAWING NO. 2339-13