


CORNER RECORD

COUNTY OF Marin T. _____ R. _____ MERIDIAN _____ CALIFORNIA

CORNER TYPE GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Set 3/4" I.D. iron pipe with plastic plug "LS 3775"; at northwest corner of Lot 39; "Map of Del Mesa"; recorded in Book 5 of Maps at Page 56; Marin County Records.

AP #71-062-15

Survey #1651

PHYSICAL DESCRIPTION OF MONUMENTS RESULT OR PERPETUATED


AS SHOWN

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD

STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY _____ OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR ACT ON December 10, 1987

SIGNED: [Signature]

L.S. or R.C.E. No. LS 3775 exp. 12-31-91

Professional Seal: JOSEPH CORRIPIET, No. 3775, LAND SURVEYOR OF CALIFORNIA

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED AND EXAMINED AND FILED 1-6 1988

BY: [Signature]

TITLE: Map 10 29

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET EX. 15

Professional Seal: ROBERT BARRELL, CIVIL ENGINEER, No. 630212, STATE OF CALIFORNIA

CORNER RECORD

COUNTY OF Marin T. _____ R. _____ MERIDIAN _____ CALIFORNIA
 CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH
 Set 3/4" I.D. iron pipe with plastic plug "LS 3775"; at northeasterly corner of Lot 39; "Map of Del Mesa"; recorded in Book 5 of Maps at Page 56; Marin County Records.


AP #71-062-15 Survey #1651

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

AS SHOWN


CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



SURVEYOR'S CERTIFICATE
 THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON December 10 1987
 SIGNED: [Signature]
 L.S. or R.C.E. No. LS 3775 exp. 12-31-92

COUNTY SURVEYOR'S CERTIFICATE
 THE CORNER RECORD WAS RECEIVED AND EXAMINED AND FILED 1-6 1988
 BY: [Signature]
 TITLE: Deputy
 DOCUMENT No. _____
 STATEMENT ON BACK OF SHEET ex. 3




CORNER RECORD

COUNTY OF Marin T. _____ R. _____ MERIDIAN _____ CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Set lead plug with brass nail and tag "LS 3775" at the southeasterly corner of Lot 39; "Map of Del Mesa"; recorded in Book 5 of Maps at Page 56; Marin County Records.


AP #71-062-15 Survey #1651

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

AS SHOWN

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)




SURVEYOR'S CERTIFICATE
 THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON December 10 1988 No. 3775
 SIGNED: _____
 L.S. or R.C.E. No. LS 3775 exp. 12-31-91
 OF CALIFORNIA

COUNTY SURVEYOR'S CERTIFICATE
 THE CORNER RECORD WAS RECEIVED AND EXAMINED AND FILED BY: DARRELL 1988 C 30212
 TITLE: REPRODUCTION
 DOCUMENT No. _____
 STATEMENT ON BACK OF SHEET

CORNER RECORD

COUNTY OF Marin T. _____ R. _____ MERIDIAN _____ CALIFORNIA
 CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH
 Set 3/4" I.D. iron pipe with plastic plug "LS 3775"; at Begin Curve (R=10) of Lot 39: "Map of Del Mesa"; recorded in Book 5 of Maps at Page 56; Marin County Records.


AP #71-062-15 Survey #1651

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED


AS SHOWN

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____


SKETCH: (Include reference tie or witness points, remarks and topo of area)



SURVEYOR'S CERTIFICATE
 THIS CORNER RECORD WAS PREPARED BY ROBERT GRITTY IN THE
 DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT
 ON December 10 1988
 SIGNED: [Signature]
 L.S. or R.C.E. No. LS 3775




COUNTY SURVEYOR'S CERTIFICATE
 THE CORNER RECORD WAS RECEIVED _____ AND EXAMINED AND FILED _____
 BY: [Signature]
 TITLE: Depto. Grava
 DOCUMENT No. _____
 STATEMENT ON BACK OF SHEET



CORNER RECORD

COUNTY OF Marin T. _____ R. _____ MERIDIAN _____ CALIFORNIA
 CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER RESULT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH
 Set 3/4" I.D. iron pipe with plastic plug "LS 3775"; at the End Curve (R=10') of Lot 39; "Map of Del Mesa"; recorded in Book 5 of Maps at Page 56; Marin County Records.


AP #71-062-15 Survey #1651

PHYSICAL DESCRIPTION OF MONUMENTS RESULT OR PERPETUATED

AS SHOWN

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



SURVEYOR'S CERTIFICATE
 THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON December 10 1987
 SIGNED [Signature]
 L.S. or R.C.E. No. LS 3775 NO. 3775
 OF CALIFORNIA

COUNTY SURVEYOR'S CERTIFICATE
 THE CORNER RECORD WAS RECEIVED AND EXAMINED AND FILED 1-10-88 1988
 BY: [Signature] C 30212
 TITLE: Depto. [unclear]
 DOCUMENT No. _____
 STATEMENT ON BACK OF SHEET

