

CORNER RECORD


Document Number A.P.N. 071-071-29

City of MILL VALLEY

County of MARIN, California

Brief Legal Description PARCEL 4, 5 P.M. 70

CORNER TYPE COORDINATES (Optional)



Government Corner Control
Meander Property
Rancho Other
Date of Survey 11/14/07

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND PIPE AND TAG PER 5 P.M. 70 UNDER PAVEMENT, SET NAIL AND TAG,

L.S. 4694 ON SURFACE OF PAVEMENT AS SHOWN ON SHEET 2.

A description of the physical condition of the monument as found and as set or reset: SEE SHEET 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on NOVEMBER 14 2007

Signed *Laurence P. Doyle* P.L.S. or R.C.E. No. P.L.S. 4694



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JANUARY 14, 2008

and examined and filed FEBRUARY 13, 2008

Signed *[Signature]* P.L.S. or R.C.E. No. 7128

Title COUNTY SURVEYOR

County Surveyor's Comment _____

