


CORNER RECORD

Documented Number 072-101-23

City of Ross

County of Marin, California

Brief Legal Description Parcel A 16 PM 66



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other

COORDINATES(Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation _____

Date of Survey 2/13/2013

Vert. Datum: NGVD 29 NADV88

Meas. Units: Metric Imperial

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Reestablish the Northerly line of Parcel A of 16 PM 66 from found original three quarter inch iron pipes tagged LS 3783 at the Northeasterly and Northwesterly corners of said Parcel A and also at the angle point in said Northerly line (note: the Northerly line is common with the Southerly line of Parcel B of 16 PM 66). See sketch on reverse side for details.

A description of the physical condition of the monument as found and as set or reset: Set one half inch rebar with yellow plastic cap affixed to top of rebar and driven flush to surrounding grade. The cap is stamped "Scranton, PLS 5379". Points were set on the Northerly line at randomly spaced intervals. See sketch on reverse side for specific locations of points set.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on February 18, 2013

Signed Douglas J. Scranton P.L.S. or R.C.E. No.: PLS 5379

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received FEBRUARY 26, 2013 and examined

and filed MARCH 28, 2013

Signed Richard G. Simonitch P.L.S. or R.C.E. No.: 7821

Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____

