


# CORNER RECORD

Agency Index DPW # 17-124  
 Document Number APN 072-231-23

City of Ross County of Marin, California  
 Brief Legal Description Doc. No. 1676017-64, M.C.R. Lying within the Rancho Punta De Quentin.



- CORNER TYPE**
- Government Corner     Control  
 Meander                     Property  
 Rancho                         Other

Date of Survey October 26, 2017

- COORDINATES (Optional)**
- N. \_\_\_\_\_ E. \_\_\_\_\_  
 Elevation \_\_\_\_\_  
 Units  Metric  U.S. Survey Foot  
 Horizontal Datum \_\_\_\_\_  
 Zone \_\_\_\_\_ Epoch Date \_\_\_\_\_  
 Vertical Datum \_\_\_\_\_  
 Complies with Public Resources Code §§8801-8819  
 Complies with Public Resources Code §§8890-8902

- PLS Act Ref.:  8765(d)     8771     8773     Other:
- Corner/Monument:  Left as found     Established     Rebuilt     Pre-Construction  
 Found and tagged     Reestablished     Referenced     Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:  
 See sheet #2 for description(s):

Found 5/8" rebar with caps PLS 7053 in good condition along the easterly boundary of subject parcel.  
 Found 3/4" iron pipe and nail and tag RCE 30465 in good condition along the southern boundary of the subject parcel. Accepted, held and used to establish and set a 3/4" iron pipe with cap LS 9077 at the southeasternmost corner of subject parcel per Record of Survey 08-150. Set two 3/4" iron pipes with cap LS 9077 as additional line points on the southern boundary of subject parcel as shown on page 2.

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with  
 the Professional Land Surveyors' Act on October 26, 2017  
 Signed *John C. Pawson* P.L.S. or R.C.E. No. PLS 9077



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received NOVEMBER 27, 2017  
 and examined and filed DEC. 05, 2017  
 Signed *[Signature]* P.L.S. or R.C.E. No. 9292  
 Title DEPUTY C.S.



County Surveyor's Comment

