


CORNER RECORD

Document Number 73.152.09
County of MARIN, California

City of ROSS

Brief Legal Description 2000 MAPS 203



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 5/2 & 9/26 2007

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

REESTABLISH THE SOUTHERLY CORNERS OF 2000 MAPS 203
& A PORTION OF THE WESTERLY LINE OF SAME SAID
MAP (2000 MAP 203 PREVIOUSLY DONE BY THIS OFFICE)
SEE SKETCH ON REVERSE SIDE

A description of the physical condition of the monument as found and as set or reset:

set 1/2" rebar with PLS CAP 5379 AFFIXED TO
TOP & DRIVEN FLUSH WITH SURROUNDING
GRADE

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on October 15 2007

Signed Douglas J. Scanlon P.L.S. or R.C.E. No. PLS 5379



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received OCTOBER 17, 2007

and examined and filed NOVEMBER 19, 2007

Signed [Signature] P.L.S. or R.C.E. No. 7128

Title COUNTY SURVEYOR



County Surveyor's Comment _____

PREPARED BY: DOUGLAS J. SCANLON SURVEYING NOVATO CA