


CORNER RECORD

Document Number A.P.# 073-232-44

City of ROSS

County of MARIN, California

Brief Legal Description 21 P.M. 28



CORNER TYPE

COORDINATES (Optional)

Government Corner Control

Meander Property

Rancho Other

Date of Survey 12/7/15

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
FOUND HUBS AND TAGS LS 3221, RESET TAGS ON 3/4" IRON PIPES

A description of the physical condition of the monument as found and as set or reset: SEE SHEET 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on DECEMBER 7 2015

Signed Lawrence P Doyle P.L.S. or R.C.E. No. P.L.S. 4694



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received DECEMBER 14, 2015

and examined and filed FEBRUARY 2, 2016

Signed Richard S. Simonitch P.L.S. or R.C.E. No. 7821

Title County Surveyor

County Surveyor's Comment LS 3221 tags reset onto 3/4" I.P.'s





PARCEL "A"
21 P.M. 28

PARCEL "B"
21 P.M. 28

PARCEL #2
5 P.M. 23

S23°12'26"W 31.21'
40.55' S06°24'58"W
N89°44'09"E 115.06'

LAGUNITAS ROAD

LEGEND

■ FOUND HUB & TAG, L.S. 3221,
RESET TAG IN 3/4" PIPE



CORNER RECORD PARCEL "A", 21 P.M. 28 ROSS MARIN COUNTY CALIFORNIA		DRAWN BY: SHEET 1 OF 1
SCALE: 1" = 40'	DATE: 12/7/15	
LAWRENCE P. DOYLE LAND SURVEYOR/CIVIL ENGINEER 100 HELENS LANE MILL VALLEY CA 94941 (415-388-9585)		DRAWING NO. 2532-CR