


CORNER RECORD

Document Number _____

City of Ross

County of Marin, California

Brief Legal Description Being Lot 7B, Map of Raymond Tract Sub #2 (2RM35)



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey Feb 17, 2007

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found Monuments as shown on Record of Survey (33 ROS 13) See Page 2.


A description of the physical condition of the monument as found and as set or reset: Set 3/4" Iron Pipe w/ Plastic Cap "LS 5814", See Page 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on 4/30/07

Signed William Schroeder P.L.S. or R.C.E. No. 5814



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUGUST 16, 2007

and examined and filed SEPTEMBER 18, 2007

Signed _____ P.L.S. or R.C.E. No. 7128

Title COUNTY SURVEYOR



County Surveyor's Comment _____