


CORNER RECORD

Document Number _____
 City of Kentfield County of Marin, California
 Brief Legal Description Lot 283 Map of Kent Woodlands #8, 6 RM 36A



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial


Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found standard street monuments per 6 RM 36A, see page 2.

A description of the physical condition of the monument as found and as set or reset: Set 3/4" iron pipe with plastic cap "LS 5814, see page 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on 4/30/07
 Signed William E. Schroeder P.L.S. or R.C.E. No. 5814



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUGUST 16, 2007
 and examined and filed SEPTEMBER 18, 2007
 Signed [Signature] P.L.S. or R.C.E. No. 7128
 Title COUNTY SURVEYOR



County Surveyor's Comment _____