


CORNER RECORD

COUNTY OF MARIN T. _____ R. _____ MERIDIAN CALIFORN

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Set a 3/4" iron pipe with plastic plug embossed "LS 3775" at the most southwesterly corner of lot 292 per "Map of Kent Woodlands Subd. No. Eight" recorded in book 6 of Maps at page 36, Marin County Records, from which a set witness 3/8" spike and shiner bears N72°47'W 16.80'

AP 74-192-13. Smith J-1407

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED


As Shown

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD

STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON July 25 1985

SIGNED: *[Signature]*

L.S. or R.C. No. LS 3775

STATE OF CALIFORNIA

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED AND EXAMINED AND FILED BY [Signature] 1985

STATE OF CALIFORNIA

DOCUMENT No. _____


STATEMENT ON BAL. _____

CORNER RECORD

COUNTY OF MARIN T. _____ R. _____ MERIDIAN _____ CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Set a 3/4" iron pipe with plastic plug embossed "LS 3775" at the most northerly corner of lot 292 per "Map of Kent Woodlands Subdivision No. Eight" recorded in book 6 of Maps at page 36, Marin County Records, from which a set witness 3/8" spike and shiner bears N71°04'W 28.41'


AP 74-192-13 Smith J-1407

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

As Shown

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (N) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)




SURVEYOR'S CERTIFICATE
 THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON July 25 1985
 SIGNED: *Joseph Grippi*
 L.S. or R.C.E. No.: LS 3775
 STATE OF CALIFORNIA

COUNTY SURVEYOR'S CERTIFICATE
 THE CORNER RECORD WAS RECEIVED AND EXAMINED AND FILED 1985
 NO. C-23341
 TITLE: _____
 DOCUMENT No. _____
 STATEMENT ON BACK OF SHEET YES NO

CORNER RECORD

COUNTY OF _____ T. _____ R. _____ MERIDIAN _____ CALIFORNIA
 CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER RESULT


PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH
 Set a 3/4" iron pipe with plastic plug embossed "LS 3775" at the most southeasterly corner of lot 292 per "Map of Kent Woodlands Subd. No. Eight" recorded in book 6 of Maps at page 36, Marin County Records, from which a found 3/4" iron pipe with tag RCE 9626 bears S20°10'43" E 0.49'

AP 74-192-13. Smith J-1407


PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED
 As Shown

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____


SKETCH: (Include reference tie or witness points, remarks and topo of area)



SURVEYOR'S CERTIFICATE
 THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE SURVEYORS ACT ON July 25 1985
 SIGNED: *[Signature]*
 L.S. or R.C.E. No. LS 3775




COUNTY SURVEYOR'S CERTIFICATE
 THE CORNER RECORD WAS RECEIVED AND EXAMINED AND FOUND CORRECT AND TRUE ON July 25 1985
 BY: *[Signature]*
 TITLE: CIVIL
 DOCUMENT No. _____
 STATEMENT ON BACK OF SHEET



CORNER RECORD

COUNTY OF MARIN T. _____ R. _____ MERIDIAN _____ CALIFORNIA
 CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH
 Found an old 2" x 2" redwood hub and replaced with a 3/4" iron pipe with plastic plug embossed "LS 3775" at the most easterly corner of lot 292 per "Map of Kent Woodlands Subd. No. Eight" recorded in book 6 of Maps at page 36, Marin County Records.

AP 74-192-13


Smith J-1407

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

As Shown


CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



SURVEYOR'S CERTIFICATE
 THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON July 25 1985

SIGNED: Joseph G. Smith
 L.S. or R.C.E. No. LS 3775



COUNTY SURVEYOR'S CERTIFICATE
 THE CORNER RECORD WAS RECEIVED 1 Aug 1985 AND EXAMINED AND FILED NO. C 2221 1985

BY: [Signature]
 TITLE: CIVIL
 DOCUMENT No. _____
 STATEMENT ON BACK OF SHEET YES NO

