
CORNER RECOR	7				Number 100-1		
Brief Legal Description O	ean View Aver						
CORNER TYPE					COORDINATES (Optional)		
+	Government Corner Meander		Control Property		E Zone NAD83 Epoch	NAD27 🗆 N	IAD83 🗆
	Rancho Date of Survey		Other		Elev		ND88 □
Corner - Left as for	ound Found and ta	gged	☐ Estat	olished [☐ Reestablished	☐ Rel	built 🕱
Identification and type of cor	ner found: Evidence used	to ider	ntify or proce	edure us	ed to establish or ree	stablish the	corner:
Found concrete	Avenue	<u>as</u>	SNOWY	1 011	~00 IIII		
See Sketch on	Back						
A description of the physical	condition of the monumer	nt as fo	ound and as	set or re	eset:		
Monuments u destroyed	iere on the	SUN	tace,	and	being sla		
Concrete monum	.				4		County
	SURVEYOR'S STATEM	ENT				707	צן ושיייוקט
This Corner Record was pr	epared by me or under r	ny dire	ection in co	nforman	ce with	SURVEYOR	
the Land Surveyor's Act on	Brogan PLS or F) 7		576	Z GENS	EL BROS 10	* S
Chief of Surve	ys - DPW M UNTY SURVEYOR'S STA	Navi Teme	n Cour	vty	W	17E OF CHI	
This Corner Record was rec	eived FEBRUAF	ZY .	5,200)4		AND SUP	
and examined and filed						ACACACA	
Signed		R.C.E.	No. <u>712</u>	<u>- iP</u>		12-31-10	双
Title COUNTY EU	RVEYOR				ON IN	o. 7128	
County Surveyor's Comm	ent		and the second s	<u> </u>		Constant of the constant of th	
					,		No. of the Control of
		***************************************				· · · · · · · · · · · · · · · · · · ·	



2007 MAPS 41