


CORNER RECORD

Document Number A.P. # 100-271-22City of _____ County of Marin, CaliforniaBrief Legal Description Lbt 98, Oceana Marin Unit 3, R.M. 14-58

CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☒
Rancho ☐ Other ☐
Date of Survey October 30, 1992

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Reestablished most southerly corner of Lot 98, Oceana Marin Unit 3,

R.M. 14-58, using found monuments per said map. Corner was destroyed due to
storm drainage construction.

Bodega Bay

A description of the physical condition of the monument as found and as set or reset:

Set 1/2" iron pipe tagged R.C.E. 24916, at the most southerly corner of
Lot 98, Oceana Marin Unit 3, R.M. 14-58.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyors' Act on November 9 19 92.

Signed Bonnie A. Mogel L.S. or R.C.E. Number R.C.E. 24916
Bonnie A. Mogel

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 11-18 19 92 and examined
and filed 11-18 19 92.

Signed Sanh Mali Title Dep. County Surveyor

County Surveyor's Comment _____

