


# CORNER RECORD

Document Number A.P.N. 104-170-22

City of Marshall

County of Marin, California

Brief Legal Description Parcel 3, 22555 State Route 1, 1 PM 35 and 6 OS 19.



**CORNER TYPE**

Government Corner  Control   
 Meander  Property   
 Rancho  Other

Date of Survey 23 August 2011

**COORDINATES(Optional)**

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone                      NAD27N  AD83   
 NAD83 Epoch \_\_\_\_\_  
 Elev. \_\_\_\_\_  
 Vert. Datum: NGVD29  NADV88   
 Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
Found Bolt, Nail and Tag L.S. 2535, Found 1/2" Iron Pipe, Nail and Tag L.S. 2535 and  
Found 1" Iron Bar, No Tag, per 6 OS 19.

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_  
Set NW corner, Nail and Tag in Tree Root, on Parcel 3, See Exhibit "A".

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with  
 the Land Surveyor's Act on AUGUST 29, 2011.

Signed [Signature] P.L.S. or R.C.E. No.: 18221



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received AUGUST 31, 2011 and examined  
 and filed SEPTEMBER 13, 2011

Signed [Signature] P.L.S. or R.C.E. No.: 7128

Title COUNTY SURVEYOR

County Surveyor's Comment \_\_\_\_\_





**ILS ASSOCIATES, INC. ©**  
 Civil Engineering & Land Surveying  
 79 Galli Drive, Suite A  
 Novato, Ca 94949-5717  
 (415)883-9200 FAX (415)883-2763

DRAWN:

SJM

JOB NO:

8580

DATE:

8/26/11

SHEET NO.

2 OF 2

# EXHIBIT A

