


**CORNER RECORD**

Document Number 112.251.14

City of INVERNESS

County of \_\_\_\_\_, California

Brief Legal Description APN 112.251.14 SURVEYED PER 31053



**CORNER TYPE**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 2-12-2008

**COORDINATES (Optional)**

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

REESTABLISH THE NORTHEAST CORNER OF  
APN 112.251.14 AS SURVEYED PER 31053;  
SEE REVERSE SIDE FOR DETAILS OF POINTS  
FOUND OF SAID 3105 TO REESTABLISH CORNER

A description of the physical condition of the monument as found and as set or reset:


set 1/2" rebar with yellow PLASTIC CAP  
AFFIXED TO TOP embossed "SCRANTON,  
PLS 5379". TOP OF CAP DRIVEN flush to  
SURROUNDING grade ON LEDGE of SAND Step

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act of FEBRUARY 18 2008

Signed Douglas J. Scranton P.L.S or R.C.E. No. PLS 5379



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received FEBRUARY 22, 2008

and examined and filed MARCH 12, 2008

Signed \_\_\_\_\_ P.L.S or R.C.E. No. 7128

Title COUNTY SURVEYOR



County Surveyor's Comment \_\_\_\_\_

JH 10604

PREPARED BY: DJ SCRANTON SURVEYING NOVATO, CA