



CORNER RECORD


SUITE 27
77 MARK DRIVE
SAN RAFAEL, CA 94903

Document Number 119-162-09

City of Point Reyes

County of Marin, California

Brief Legal Description Parcel "A" 5 P.M. 69



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey Nov. 13, 1999

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Pipe and tag LS 3616 found at corners per

5 P.M. 69


A description of the physical condition of the monument as found and as set or reset: _____

See plat on back.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on November 13 19 99.

Signed [Signature] L.S. or R.C.E. Number LS 3887



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 12-3 19 99 and examined and filed 12-6 19 99.

Signed [Signature] Title DEPUTY



County Surveyor's Comment _____

